



# Hours Lost Due to Work Related Injury/Illness Air Pollution Control





KPI Owner: Keith Talley

Process: Safety

Baseline, Goal, & Benchmark		Source Summary	Continuous Improvement Summary		
Baseline: 0 hours lost Goal: To maintain hours lost at zero.   Benchmark: TBD		Data Source: Payable Time PeopleSoft  Goal Source: Scope Summary  Benchmark Source: TBD	Plan-Do-Check-Act Step 8: Monitor and diagnose Measurement Method: The total number of hours per month employees were absent due to a work place injury or an illness contracted at work, rate calculated by dividing by total standard hours Why Measure: Minimize number & severity of workplace injuries/illness Next Improvement Step: Continue to engage employees in safety training and maintain awareness of Metro policies.		
How Are We Doing?					
03.01.15-02.27.16 12 Month Goal	03.01.15-02.27.16 12 Month Actual		02.14.16-02.27.16 Goal	02.14.16-02.27.16 Actual	
0	0		0	0	
Hours	Hours		Hours	Hours	

## Hours Lost Due to Work Related Injury/Illness



Root cause analysis is not necessary because there is no gap between the goal and current performance.